

Costs for WO #02-60456-0 AND ALL ASSOCIATED SUBS

MO.NO.....	Description.....	Part No	Part Noun Qual.....	Part Qty Issued	Tot Material Act	Act Tot Labor Cost	Actual Tot Cost
		D	REPAIR AND RETURN: ACTUATOR, S/N 30994803, JORDAN CONTROLS M/N SM-5220-N-1-30/1000-90 0007 F001	0			
		D	LABOR AND MATERIAL FOR ELECTRICAL INSTALLATION OF OVERFIRE AIR CONTROL DAMPERS, IGS02-14, UNIT 1	0			
		D	INVOICE NO. 6387-3 COMPLETED BOILER MODEL, GENERAL ARRANGEMENT, AND MANUFACTURING DRAWINGS; RAW MATERIAL ORDERED & DELIVERED; MANUFACTURING COMPLETED; UNIT PREPPED FOR INSTALLATION OF NEW MATERIALS; CONSTRUCTION COMPLETED	0			
		D	IRWIN INVOICE #72084336 STEAM DRUM MOD	0			
		D	INVOICE NO. 293-001 R1 OVERFIRE AIR CONTROL DAMPER INSTALLATION FOR MARCH	0			
		71315	GAS, CALIBRATION	1			
		73562	GAS, CALIBRATION	1			
		D	MODULE, INPUT, FOXBORO P/N 3A4-I2DA	0			
		D	MODULE, OUTPUT, FOXBORO P/N 3A2-D2IB	0			
		D	HAT, IPSC, FOR TEI CONTRACTOR	0			
		D	INVOICE NO. 293-002-R1 ELECTRICAL WORK FOR OVERFIRE AIR	0			
		D	MATERIALS AND DOCUMENTATION FOR UNIT 2 STEAM DRUM INTERNAL MODIFICATIONS PER BABCOCK & WILCOX PROPOSAL P-4572, DATED AUGUST 5, 2003	0			
		D	INVOICE NO. 6570-5	0			

IP7_039435